



SERVICE ORDER

PREPARED BY : MS. VALENTINA T.
TECHNICIAN : MR. SATILIO LIBUI
: MR. VERTI MEDAN

OFFICE/CUSTOMER COPY
W.O : LTA/WO/RG/24/00026
W.O DATE : 15-10-2024

JOB DESCRIPTION	ASSIGN TO
TROUBLESHOOT-GATEWAY REPLACEMENT AZ30081457 TO RN40082191	NAME : MR. LEO TAN COMPANY NAME : LTA SERVICES SDN. BHD. CONTACT CO : 013-8089273

BUILDING INFO	
ID	: 15829
COMPANY NAME	: GOLDENBAY HOTEL.
BUILDING NAME	: GOLDENBAY HOTEL.
ADDRESS	: LOT 3493 BINTULU TOWN, JALAN TUN RAZAK, 97000 BINTULU, SARAWAK.
CONTACT NO	: i) 016-8677170 - GRACE SEE SHIAU TIIN. ii) 013-8627173 - CAROLINE ANAK AMBON.
MFAP TYPE	: ADDRESSABLE
MFAP BRAND	: NOTIFIER
INSTALLATION DATE	: 30-11-2018

SPKA PANEL			
SERIAL NUMBER	RN40082191	SIM NUMBER	8960012206946240781
TELCO	MAXIS		
NETWORK STATUS	-70dBm%	MCB CONDITION	GOOD
GATEWAY CONDITION	GOOD	BATTERY TEST	GOOD
PANEL CONDITION	GOOD	AC RELAY CONDITION	GOOD
MFAP CONDITION	GOOD	MFAP CONDITION REMARK	
TERMINATION CONTACT	RELAY		

ALARM TESTING			
MFAP TRIGGER ALARM	BYPASS	REMARK	
SMS RECEIVE	YES	REMARK	
RECEIVE CALL FROM IMC	YES	REMARK	
COMMENT:	SISTEM SPKA BERFUNGSI DENGAN BAIK. PIC ADA TERIMA SMS DAN PANGGILAN DARI SPKA.		

PERSON IN CHARGE CHANGE			
FULL NAME :		FULL NAME :	
MOBILE NUMBER :		MOBILE NUMBER :	
EMAIL :		EMAIL :	
POSITION :		POSITION :	
LTA SERVICES SDN BHD		SUBSCRIBER	
DATE : 17-10-2024		DATE : 17-10-2024	
NAME : VERTI MEDAN		NAME : SULAIMAN	
POSITION : TECHNICIAN		POSITION : MAINTENANCE	



Other Comments or Special Instruction
1. Completion of work within 7 days after work order is issued. 2. After completing the work, please send the claim within 30 days



LTA SERVICES SDN. BHD. (705567-V)
 2ND FLOOR, LOT 113, PLOT 24, GALA CITY,
 JALAN TUN JUGAH, 93350, KUCHING, SARAWAK
 EMAIL: Itaspka1@gmail.com TEL: 082-265761
 www.ltaservicesdnbhd.com

DELIVERY ORDER

OFFICE/CUSTOMER COPY

GOLDENBAY HOTEL.

NO: LTA/DO/RG/24/00026

LOT 3493 BINTULU TOWN, JALAN TUN RAZAK, 97000 BINTULU, SARAWAK.

DATE: 15-10-2024

ATTN: 016-8677170 - GRACE SEE SHIAU TIIN. / 013-8627173 - CAROLINE ANAK AMBON.

ITEM NO	ITEM DESCRIPTION	QTY	
	Supply and install one unit iFSP new gateway replacement - TROUBLESHOOT-GATEWAY REPLACEMENT		
1 iSNET-MI	iFSP S.N : RN40082191 Battery S.N : ID : 15829	1	LOT

LTA SERVICES SDN BHD

DATE: 17-10-2024
 NAME: VERTI MEDAN
 POSITION: TECHNICIAN



RECEIVED BY

DATE: 17-10-2024
 NAME: SULAIMAN
 POSITION: MAINTENANCE
 COMPANY : GOLDENBAY HOTEL