



**SERVICE ORDER**

PREPARED BY : MS. VALENTINA T.  
TECHNICIAN : MR. SATILIO LIBUI  
: MR. VERTI MEDAN

**OFFICE/CUSTOMER COPY**  
W.O : LTA/WO/24/00187  
W.O DATE : 21-10-2024

JOB DESCRIPTION	ASSIGN TO
IRT-RENEWAL 14-11-2024 TO 13-11-2025	NAME : MR. LEO TAN COMPANY NAME : LTA SERVICES SDN. BHD. CONTACT CO : 013-8089273

BUILDING INFO	
ID	: 16860
COMPANY NAME	: SHIN YANG PLYWOOD (BINTULU) SDN. BHD.
BUILDING NAME	: SHIN YANG PLYWOOD (BINTULU) SDN. BHD.
ADDRESS	: LOT 813, BLOCK 38, KEMENA INDUSTRIAL ESTATE P.O. BOX 1899, 97010 BINTULU, SARAWAK.
CONTACT NO	: i) 016-8695381 - FELIX WONG JING KING. : ii) 016-8793171 - WONG CHUNG MAIW.
MFAP TYPE	: ANALOG
MFAP BRAND	: PROGRAM ELECTRONIC
INSTALLATION DATE	: 14-11-2018

SPKA PANEL			
SERIAL NUMBER	RN40080407	SIM NUMBER	8960012003737314879
TELCO	MAXIS		
NETWORK STATUS	-67DBM%	MCB CONDITION	GOOD
GATEWAY CONDITION	GOOD	BATTERY TEST	GOOD
PANEL CONDITION	GOOD	AC RELAY CONDITION	GOOD
MFAP CONDITION	GOOD	MFAP CONDITION REMARK	
TERMINATION CONTACT	DRY CONTACT		

ALARM TESTING			
MFAP TRIGGER ALARM	MFAP	REMARK	
SMS RECEIVE	YES	REMARK	
RECEIVE CALL FROM IMC	YES	REMARK	
<b>COMMENT:</b>	SISTEM SPKA BERFUNGSI DENGAN BAIK. PIC ADA TERIMA SIGNAL DARI SPKA KETIKA PERCUBAAN ALARM DILAKUKAN.		

PERSON IN CHARGE CHANGE	
FULL NAME :	FULL NAME :
MOBILE NUMBER :	MOBILE NUMBER :
EMAIL :	EMAIL :
POSITION :	POSITION :

LTA SERVICES SDN BHD

SUBSCRIBER

DATE : 22-10-2024  
NAME : SATILIO LIBUI  
POSITION : TECHNICIAN



DATE : 22-10-2024  
NAME : SOPUANI BIN ROSLEE  
POSITION : SUPERVISOR

Other Comments or Special Instruction
1. Completion of work within 7 days after work order is issued. 2. After completing the work, please send the claim within 30 days